


AeroKits... www.aerokits.net.au

Savannah Tip No 14: *For those with the 100HP Rotax with the Kit supplied airbox, it has been found that the air inlet pipe into the airbox chafes against the top of the air filter element, and will eventually wear a series of holes in the ridges of the element. See photo.*



Close Up Below.



This problem is easily fixed by bending upwards the end of the inlet pipe to provide clearance on the filter element. See Photo.

