

**Tip No 4:** *I have seen some instances of the engine frame bolt heads chafing the cooling hoses on the underside of the Rotax engine. Even if the hoses were not contacting the bolt heads at installation the hoses can sag a little with time and vibration and rub on the bolt heads. We need to cable tie some rubber insertion at these points to prevent chafing.*

