

Tip No 9: We need to check that the Front Fork Steering Arms are not chafing the heater Skeet Hose which is fitted between the muffler and the heater inlet on the firewall. A couple of cable ties as per the photo will keep the hose away from the arms. This fix is a bit ugly and perhaps someone will have a better idea that is light and economical.



You can find all previous Savannah Tips and products on my [Web Site here.](#)